

# Inspection Photos

API: 05-071-08351

Operator: TIMBER CREEK OPERATING

Inspection Date: 1/30/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-071-08351 | Date: 1/30/2020

## Inspection Photos



**Photo 1.** Facing west toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-08351 | Date: 1/30/2020

## Inspection Photos



**Photo 2.** Well sign is posted at meter house.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-08351 | Date: 1/30/2020



## Inspection Photos



**Photo 3.** The lid is open on the tank. There are signs of spillage out of the tank.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-08351 | Date: 1/30/2020

## Inspection Photos



**Photo 4.** There is pipe riser with no LO/TO and clearly visible . The steel covers need to be placed to avoid entry.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-08351 | Date: 1/30/2020



## Inspection Photos



**Photo 5.** There is oily waste in the engine skid.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-08351 | Date: 1/30/2020

## Inspection Photos



**Photo 6.** There is oily waste at the engine skid at the separator.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-08351 | Date: 1/30/2020



## Inspection Photos



**Photo 7.** The muffler on the engine is broke apart causing the engine to be very loud. Needs to be maintained in good mechanical condition.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-08351 | Date: 1/30/2020