

**Inspection Photos**  
**Location Name: Candelaria 33-5 FEE 10U #3**  
**API: 05-007-06215**



**Candelaria 33-5 FEE 10U #3 pump jack.**



**Secondary containment for lube oil container is almost full of ice.**

**Inspection Photos**  
**Location Name: Candelaria 33-5 FEE 10U #3**  
**API: 05-007-06215**



**Inadequate secondary containment for lube oil container.**



**Fencing supplies stored near pump jack.**