

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/24/2020

Submitted Date:

01/24/2020

Document Number:

699800453

FIELD INSPECTION FORM

Loc ID 334347 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus		COGCC.inspections@caerusoilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284301	WELL	PR	07/01/2019	GW	077-09051	RADEL 11-12 (OL11)	PR
284302	WELL	PR	09/01/2019	GW	077-09050	RADEL 10-9 (OL11)	PR
284303	WELL	SI	08/01/2019	GW	077-09049	RADEL 10-16(OL11)	SI

General Comment:

[COGCC Inspection Report Summary](#)
On Friday 1/24/20 at approximately 13:00 hours, I, Inspector Corey De Paolo, conducted a follow up inspection at CAERUS PICEANCE LLC RADEL-68S96W /11NWSW, Location #334347 in Mesa County Colorado.
Refer to document #699800205 inspection conducted on 12/16/19. Not all corrective actions have been completed. While there, I observed normal production operations.
During this inspection the following possible compliance issues were observed: Multiple holes in tank containment liner. See photo #0464, #0465 and #0466 with a previous corrective action date of 1/16/20.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Type: Bird Protectors	# 3	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Centralized containment. Multiple holes in tank containment liner. See photo #0464, #0465 and #0466.			
Corrective Action:	Berms or other secondary containment devices shall be sufficiently impervious to contain any spilled or released material. Patch all holes in tank containment liner.			Date: 01/16/2020

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	

Corrective Action:

Date:

Inspected Facilities

Facility ID: 284301 Type: WELL API Number: 077-09051 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID: 284302 Type: WELL API Number: 077-09050 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID: 284303 Type: WELL API Number: 077-09049 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: last produced July 2019.

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Compaction				
Compaction						
Ditches						
Berms						
		Gravel				
		Culverts				
Gravel						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402294643	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5048140
699800454	Photos for Insp. #699800453	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5048137