

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

PHOTO 4: APPEARS THAT FUEL GAS SEPARATOR IS BEING DRAINED ON LOCATION LEAVING AN AREA OF IMPACTED SOIL NEAR COMPRESSOR.

Corrective Action:

CAPTURE AND PROPERLY DISPOSE OF ANY OILY WASTE FROM FUEL GAS SEPARATOR WHEN IT IS DRAINED. PROPERLY DISPOSE OF IMPACTED SOIL

Date: 02/01/2020

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Compressor

1

Comment:

PHOTO 3: Vacuum pump observed on well without COGCC approval.

Corrective Action:

Provide COGCC with documentation showing approval of use of vacuum pump.

Date: 02/11/2020

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 288796 Type: WELL API Number: 071-09150 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402295736	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5049419
695102111	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5049412