

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/28/2020

Submitted Date:

01/28/2020

Document Number:

679602241**FIELD INSPECTION FORM**Loc ID 430787 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**17 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430780	WELL	PR	10/01/2019	OW	123-36296	Simonsen-Schaefer 7M-243	SI
430782	WELL	PR	10/01/2019	OW	123-36298	Simonsen-Schaefer 7J-403	SI
430786	WELL	PR	05/01/2019	OW	123-36301	Simonsen-Schaefer 7E-423	SI
430789	WELL	PR	10/01/2019	OW	123-36303	Simonsen-Schaefer 7J-243	SI
430921	WELL	PR	08/30/2013	OW	123-36330	Simonsen-Schaefer 7E-203	SI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained soil in separator house. See attached photo.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).d.	Date:	02/04/2020
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on location. See attached photo.		
Corrective Action:	Comply with Rule 603.f.	Date:	02/04/2020
Type	TRASH		
Comment:	Trash on location. See attached photos.		
Corrective Action:	Comply with Rule 603.f.	Date:	02/04/2020

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Compressor	# 2		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 9		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 4		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 5		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		,	
Comment:	Loadout Control Tank					
Corrective Action:						Date:

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with other tanks.				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	100 BBLS	PBV FIBERGLASS		,
Comment:					
Corrective Action:					

**Paint**

Condition	Adequate	
Other (Content)		

Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance
Comment: Shares containment with other tanks.						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	10	400 BBLs	STEEL AST		40.509100,-104.828000	
Comment:						
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance
Metal	Adequate	Walls Sufficient		Base Sufficient		Adequate
Comment:						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

**Inspected Facilities**Facility ID: 430780 Type: WELL API Number: 123-36296 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: SI; Pilot offCorrective Action: Date: Facility ID: 430782 Type: WELL API Number: 123-36298 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: SICorrective Action: Date: Facility ID: 430786 Type: WELL API Number: 123-36301 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: SICorrective Action: Date: Facility ID: 430789 Type: WELL API Number: 123-36303 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: SICorrective Action: Date: Facility ID: 430921 Type: WELL API Number: 123-36330 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: SICorrective Action: Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p><b>**Weather Conditions: sunny, muddy</b></p> <p>On Tuesday, January 28, 2020 at approximately 14:00, I, Inspector Brittani Santistevan, conducted an on-site inspection at SIMONSEN-SCHAEFER 6L-HZ PAD (PDC Energy), at location #: 430787 in WELD COUNTY Colorado.</p> <p>While there, I observed a shut in facility.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1. Trash on SW side of location and inside berm containing separators (appears to be ply wood from sound wall). PLEASE REMOVE AND COMPLY WITH RULE 603.F. (Corrective Action Date: February 2, 2020) See attached photo #13, 14.</p> <p>2. Unused equipment in berm containing separators (closest to ECDs). PLEASE REMOVE AND COMPLY WITH RULE 603.F. (Corrective Action Date: February 2, 2020) See attached photo #12.</p> <p>3. Stained soil in separator house (second one from south). CONDUCT MAINTENANCE ON EQUIPMENT, CLEAN UP STAINED MATERIAL AND REVIEW SELFINSPECTION PROCESSES. (Corrective Action Date: February 2, 2020) See attached photo #15.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	santistb	01/28/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402296973	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5050492">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5050492</a>
679602242	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5050482">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5050482</a>