

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/27/2020

Submitted Date:

01/29/2020

Document Number:

690101698

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
319656 _____ Maclaren, Joe _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10548
Name of Operator: HRM RESOURCES II LLC
Address: 410 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TROY	713) 818-8152	tmouret@p3petro.com	
Payne, Gina		gpayne@hrmres.com	
Pape, Terry		tpape@hrmres.com	
Whittington, Ellice		ellice.whittington@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
200753	WELL	PR	03/01/2018	OW	001-06156	UPRR-EHN 34-17	EG

General Comment:

[COGCC Engineering Integrity Inspection; Flowline Inspection Only. The Corrective Actions identified during this field inspection are located in the flowline section of report. Photos uploaded can be accessed via link\(s\) at end of report.](#)

Inspected Facilities

Facility ID: 200753 Type: WELL API Number: 001-06156 Status: PR Insp. Status: EG

Flowline

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: Material:
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: The off location flowline(s) (UPRR EHN 34-17 wellhead flowline) run approximately 3340' W-SW from the wellhead to facility/ battery located at the NW corner of intersection of 144th Ave and Horrogate Rd. The alignment of off location flowline(s) is indeterminate at this time; Off location flowline(s) have not been registered with COGCC; Operator has not submitted COGCC Form 44.

Note: Operator has not registered any off location flowlines with COGCC; The Corrective Action outlined is applicable to all wells operated by HRM Resources II (Painted Pegasus Petroleum LLC) with off location flowlines.

Corrective Action: Comply with the following COGCC rule (partial description of rule):

1101.a. Off-Location Flowline Registration. (1) An operator must register an off-location flowline constructed on or after May 1, 2018, by submitting a Flowline Report, Form 44, to the Director within 30 days after the flowline is placed into service. An off location flowline in existence prior to May 1, 2018, must be registered by October 31, 2019.

Date: 10/31/2019

COGCC Comments

Comment	User	Date
ALL CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE	maclarej	01/29/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402297430	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5051185
690101701	Signage and wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5051182
690101702	View W-SW from wellhead to facility	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5051183
690101703	Aerial Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5051184