

Inspection Photos
Location Name: State of Colorado "P" #1
Location ID:319692



Photo #1 tanks and debris



Photo #2 separator and combustor

Inspection Photos
Location Name: State of Colorado "P" #1
Location ID:319692





Photo #3 meter run and RTU



Photo #4 pumpjack

Inspection Photos

Location Name: State of Colorado "P" #1
Location ID:319692



Component	Mole %	Liquid Content	Mass %	Property	Total Sample	C6 Plus Fraction
Carbon Dioxide, CO2	2.3730		3.6943	Pressure Base	14.730	
Nitrogen, N2	1.2090		1.1981	Temperature Base	60.00	
Methane, C1	56.7750		32.2194	HCDF @ Sample Pressure	56.866	
Ethane, C2	14.8920	3.9989	15.8402	Crocodentherm	167.805	
Propane, C3	13.7440	3.8019	21.4386	HV, Dry @ Base P, T	1600.67	
iso-Butane, iC4	1.6540	0.5435	3.4007	HV, Sat @ Base P, T	1572.81	
n-Butane, nC4	5.4170	1.7147	11.1375	HV, Sat @ Sample P, T	1586.88	
iso-Pentane, iC5	1.1820	0.4340	3.0167	Relative Density	0.9821	
n-Pentane, nC5	1.3760	0.5008	3.5119	Fws Factor		
Hexanes Plus, C6+	1.3780	0.6038	4.5426	Free Water GPM		
Water, H2O				Stock Tank Condensate Brishmn	2.289	
Hydrogen Sulfide, H2S				26 # RVP Gasoline	1.586	
Oxygen, O2				Testcar Permian	1.700	
Carbon Monoxide, CO				Testcar Permian	2.322	
Hydrogen, H2				Testcar Midcon		
Helium, He						
Argon, Ar						
Totals	100.0000	11.5976	100.0000			

Sample
Date: 11/03/2011 Pressure: 24.0
Type: Spot Temperature: 37.0

*** End of Report ***

Feb 5, 2020 at 11:52:54 AM
N 39° 54' 58" W 104° 36' 11"

Photo #5 meter out of calibration



Photo #6 unmarked riser south of crude tank

Inspection Photos
Location Name: State of Colorado "P" #1
Location ID:319692



Photo #7 load off line with no bull plug



Photo #8 leaking valve and stained soil

Inspection Photos
Location Name: State of Colorado "P" #1
Location ID:319692



Photo #9 leaking valves



Photo #10 stained soil

Inspection Photos
Location Name: State of Colorado "P" #1
Location ID:319692



Photo #11 stained soil by combustor



Photo #12 unmarked risers by pumpjack

Inspection Photos
Location Name: State of Colorado "P" #1
Location ID:319692



Photo #13 safety equipment not in place on pumpjack