

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/05/2020

Submitted Date:

02/05/2020

Document Number:

700900018**FIELD INSPECTION FORM**Loc ID 319692 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #210City: AURORA State: CO Zip: 80016**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
200918	WELL	PR	10/01/2019	GW	001-06321	STATE OF COLORADO P 1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	debris on location (dead weeds)		
Corrective Action:	Rule 603.f . See photos #1 & 4	Date:	02/20/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Pump Jack	# 1		
Comment:	No safety cage on pulleys for pumpjack.and unmarked riser		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. See photo #13 Flowline risers not LO/TO or marked are considered unused equipment. Rule 603.f . Correction date 2/7/2020 or 3/5/2020 to remove unmarked risers. See photos #6 & 12.		Date: 03/05/2020
Type: Gas Meter Run	# 1		
Comment:	meter out of calibration		
Corrective Action:	Meter out of calibration per Rule #329 see photo #5		Date: 03/05/2020
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			
Type: Ancillary equipment	# 1		
Comment:	RTU		

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appers to be plumed to surface		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,
Comment:	shares berm with crude				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	80
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		39.915604,-104.603013
Comment:	unmarked riser next to tank				
Corrective Action:	Flowline risers not LO/TO or marked are considered unused equipment. Rule 603.f . Correction date 2/7/2020 or 3/5/2020 to remove unmarked risers. See photos #6 & 12.				Date: 03/05/2020

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 200918 Type: WELL API Number: 001-06321 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadComment: Appears to be plumbed to surface

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On February 5, 2020 at approximately 11:48am, I, Inspector Chane Finkenbinder, conducted an on-site inspection at State of Colorado "P" #1, Operator Renegade Oil and Gas Company, at API # 001- 06321 in Adams County Colorado. While there, I observed a location in Production.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Bullplug missing from load off line. Location is within a designated setback location, bullplug or cap all loadlines per Rule 604.c.(2)O. See photo # 7 Corrective action date 2/13/2020.</p> <p>Debris on location (dead weeds) Comply with Rule 603.f . See photos #1 &4 Corrective action date 2/20/2020.</p> <p>Unmarked riser. Flowline risers not LO/TO or marked are considered unused equipment. Rule 603.f . Correction date 2/7/2020 or 3/5/2020 to remove unmarked risers. See photos #6 & 12.</p> <p>Leaking valves. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Correction date 3/5/2020. See photos #8 & 9.</p> <p>No safety cage on pulleys for pumpjack. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Correction date 3/5/2020. See photo #13</p> <p>Stained soil. Control and contain spills/releases and clean up per Rule 906.a. Correction date 3/7/2020 See photos #8, 10 and 11.</p> <p>Meter out of calibration. Meter needs to be calibrated per Rule #329 see photo# 7. Corrective action Date 3/5/2020.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	finkenbc	02/05/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700900019	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5058522