

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/30/2020

Submitted Date:

01/30/2020

Document Number:

688800662

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
Hughes, Jim _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 6 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	
Beebe, Sabre		sabre.beebe@bpx.com	All Inspections
Murray, Richard		g.richard.murray@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
470891	SPILL OR RELEASE	AC	01/22/2020		-	Robertson 19 1 1	EI

General Comment:

On January 30, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Spill/Release Point ID #470891. For more information regarding this release, please refer to document #402288080.

Inspected Facilities

Facility ID: 470891 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 9

Comment: [Please refer to Spill/Release Point ID #470891 for more information regarding this release.](#)

Corrective Action: [Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.](#)

Date: 02/28/2020

Reportable: YES

GPS: Lat 37.085601

Long -107.536948

Proximity to Surface Water: _____

Depth to Ground Water: 120

Water Well Complaint:

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Lat

Long

Field Parameters:

Sample Location: _____

Comment: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Fail			Material Handling And Spill Prevention	Fail	
<p>Comment: Excavated material does not appear to have any containment structures present.</p> <p>Corrective Action: E&P waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 907. Contct COGCC EPS staff. Date: <u>02/03/2020</u></p>						
<p>Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

COGCC Comments

Comment	User	Date
<p>On January 30, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Spill/Release Point ID #470891. For more information regarding this release, please refer to document #402288080.</p> <p>During this inspection, a Crossfire construction crew and a BP representative were on site. The excavation was being backfilled, and reportedly some of the flow lines within the trench were to be abandoned.</p> <p>The operator shall submit any information that is available concerning failure analysis, integrity/pressure testing, and any data concerning the root causes of the spill. Provide all pipeline integrity data to the COGCC Western Integrity Inspector, Richard Murray, at (970) 989-3092 or g.richard.murray@state.co.us.</p>	hughesjo	01/30/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402299780	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5053929
688800663	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5053927