

Inspection Photos
Location Name: Anschutz Windmill
Location ID: 424573




Photo 1 – Wellhead, Unused wellhead parts, polish rod and Pumping Unit



Photo 2 – Unmarked Riser

Inspection Photos
Location Name: Anschutz Windmill
Location ID: 424573



Photo 3 – Unmarked Risers




Photo 4 – Unmarked Riser, south of ECD