

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/06/2020

Submitted Date:

02/06/2020

Document Number:

696301229**FIELD INSPECTION FORM**Loc ID 434251 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
James, Brian		bjames@hpres.com	All Inspections
Kraich, Adam		adam.kraich@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159790	WELL	PR	12/28/2018	OW	123-41039	Anschutz State 5-62-35-3225CN	PR
159791	WELL	PR	12/28/2018	OW	123-41040	Anschutz State 5-62-35-3225CS	PR
159792	WELL	PR	12/28/2018	OW	123-41041	Anschutz State 5-62-35-4841C	PR
159793	WELL	PR	12/28/2018	OW	123-41042	Anschutz State 5-62-35-3340C	PR
159843	WELL	PR	09/01/2018	OW	123-41064	Anschutz State 5-62-35-4956C	PR
434250	WELL	PR	10/01/2018	OW	123-38055	Anschutz State 5-62-35-6457BH	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate (x6)		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Unusued Frac Tank East of Wells, see photos		
Corrective Action:	Comply with Rule 603.f.	Date:	03/06/2020
Type	UNUSED EQUIPMENT		
Comment:	Unused Rods, wellhead parts and Pumping Unit at 5-62-35-6457BH Well, see photos		
Corrective Action:	Comply with Rule 603.f.	Date:	04/06/2020

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Generator		
Corrective Action:		Date:	
Type: Gas Meter Run	# 12		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 6		
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Line Heater		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electrical and Automation Equipment		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	159790	Type:	WELL	API Number:	123-41039	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	159791	Type:	WELL	API Number:	123-41040	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	159792	Type:	WELL	API Number:	123-41041	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	159793	Type:	WELL	API Number:	123-41042	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	159843	Type:	WELL	API Number:	123-41064	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	434250	Type:	WELL	API Number:	123-38055	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 02/05/2020 at approximately 11:28, I, Inspector Erica Petrie, conducted a Field Inspection at Anschutz State 5-62-35_36 NWSW Pad, Location ID #434251 in Weld County, Colorado.</p> <p>While there, I observed Production Operations. Winter conditions, snow covered ground at the time of Inspection.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused Frac Tank east of the 5 Well Pad. See photos. Comply with Rule 603.f. Corrective Action date 03.06.2020</p> <p>Unused Rods, wellhead parts and Pumping Unit at the 5-62-35-6457BH Well. The Well is on plunger lift now. equipment no longer needed. See photos. Comply with Rule 603.f. Corrective Action date 03.06.2020</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.</p> <p>Continuing Educational Inspections</p>	petrie	02/06/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696301230	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5059178