

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402179780

Date Received:
09/19/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Susana Lara-Mesa</u>	<u>303-825-4822</u>	<u>slaramesa@kpk.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693500947
Inspection Date: 08/05/2019 FIR Submit Date: 08/05/2019 FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC Company Number: 46290
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 318470

Location Name: COSSLETT B-61N68W Number: 2SENW County: WELD
Qtrqr: SENW Sec: 2 Twp: 1N Range: 68W Meridian: 6
Latitude: 40.082130 Longitude: -104.972810

FACILITY - API Number: 05-123-00 Facility ID: 241354

Facility Name: COSSLETT B Number: 2
Qtrqr: SENW Sec: 2 Twp: 1N Range: 68W Meridian: 6
Latitude: 40.082130 Longitude: -104.972810

CORRECTIVE ACTIONS:

1 CA# 128932

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 09/05/2019

Response: CA COMPLETED Date of Completion: 09/17/2019

Operator Comment: Mechanical issues:Pumpjack gear box leaking has been fixed.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 CA# 128933

Corrective Action: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.

Date: 09/05/2019

Response: CA COMPLETED

Date of Completion: 09/17/2019

Operator
Comment:

Stained soil around Pumping Unit base has been removed. Please see attached pictures.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 CA# 128934

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 08/06/2019

Response: CA COMPLETED

Date of Completion: 09/17/2019

Operator
Comment:

Mechanical issue: Tubing flow lines leaking has been fixed.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

4 CA# 128935

Corrective Action: Install sign to comply with Rule 210.e.

Date: 09/05/2019

Response: CA COMPLETED

Date of Completion: 09/17/2019

Operator
Comment:

Sign has been updated. Please see attached picture.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

5 CA# 128936

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e.

Date: 09/05/2019

Response: CA COMPLETED

Date of Completion: 09/17/2019

Operator
Comment:

Stained soil around wellhead has been removed. Please see attached pictures.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Steve Hamilton

Signed: _____

Title: Field Supervisor

Date: 9/19/2019 3:48:26 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402179780	FIR RESOLUTION SUBMITTED
402179800	Sign updated PIC1
402179801	Stained soil removed PIC2
402179802	Stained soil removed PIC3
402179804	Stained soil removed PIC4

Total Attach: 5 Files