

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/28/2020

Submitted Date:

02/05/2020

Document Number:

694500169**FIELD INSPECTION FORM**Loc ID 428531 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 95520Name of Operator: WESCO OPERATING INCAddress: 120 S DURBIN STREETCity: CASPER State: WY Zip: 82602**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Weinert, Dave	307-577-5329	davew@kirkwoodcompanies.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428531	LOCATION	AC			-	Maudlin Gulch Tank Battery	EI
451105	SPILL OR RELEASE	CL	07/26/2017		-	Maudlin Gulch Tank Battery	EI
467136	SPILL OR RELEASE	AC	09/03/2019		-	Maudlin tank battery	EI

General Comment:

On 1/28//2020 COGCC staff Kris Neidel was present at the Maudlin Gulch Tank battery to witness the sampling of four groundwater monitoring wells as part of Remediation Project 14686. Weather was 27 degrees, clear, snow had fallen the previous night. All wells were first gauged for water depth. Then observed for any free product by gently placing the bailer in the well, and pulling out 8-10" of water. Then all wells were purged of at least 4 casing volumes. Purged water was handled as E&P waste. Prior to collecting samples, wells were gauged again to determine that they had recovered from purging. Water collected will be sampled for COGCC 609 groundwater standards. Emissions combustor was burning at the time of inspection. The pit that is a part of REM Project 14686 is open and was cover

Inspected Facilities

Facility ID: <u>428531</u>	Type: <u>LOCATION</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>
----------------------------	-----------------------	----------------------	-------------------	-------------------------

Facility ID: <u>451105</u>	Type: <u>SPILL OR</u>	API Number: <u>-</u>	Status: <u>CL</u>	Insp. Status: <u>EI</u>
----------------------------	-----------------------	----------------------	-------------------	-------------------------

Facility ID: <u>467136</u>	Type: <u>SPILL OR</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>
----------------------------	-----------------------	----------------------	-------------------	-------------------------

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Drill Cuttings	Piles	Adequate		
Comment	The cuttings from the groundwater monitoring wells were stored in a bermed area with a plastic liner south of the old soil storage area.			
Corrective Action	The cuttings should be removed as soon as practicable, no later than June 1 2020.			Date: 06/01/2020

Spill/Remediation:

Comment:	
Corrective Action:	Date: _____

Emission Control Burner (ECB): YES _____

Comment: _____

Pilot: ON _____ Wildlife Protection Devices (fired vessels): YES _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402304503	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5058026
694500170	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5058025