

Inspection Photos  
Operator: BP America  
Location #: 333635  
Date: 1-31-2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Vegetation is largely in a dormant condition at this time with perennial grasses such as crested wheatgrass, western wheatgrass, and intermediate wheatgrass.





Photo 3. View of area within the western fill slope where snow melt is actively flowing off of the well pad, creating an erosional channel. Wattle is not functioning and is not an adequate BMP in this area.





Photo 4. View of the reference area, comprised of pinyon juniper woodland with sagebrush and gambel oak shrub and herbaceous understory.