

Banta Ridge Federal 12A-18-1-103

API: 05-103-10409

Inspection: 679707328



39.96132, -109.00484, 5948 5ft, 270°

02/11/2020 02:09:02 PM

Photo 1. Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Banta Ridge Federal 12A-18-1-103

API: 05-103-10409

Inspection: 679707328



39.96137, -109.00567, 5937.2ft, 20°

02/11/2020 02:10:51 PM

Photo 2. Pump jack & compressor building.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Banta Ridge Federal 12A-18-1-103

API: 05-103-10409

Inspection: 679707328



Photo 3. Tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Banta Ridge Federal 12A-18-1-103

API: 05-103-10409

Inspection: 679707328



Photo 4. Compressor & tank battery.



Banta Ridge Federal 12A-18-1-103

API: 05-103-10409

Inspection: 679707328



39.96134, -109.00522, 5938.5ft, 155°

02/11/2020 02:13:03 PM

Photo 5. Gas venting out around edges of hatch on middle tank.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources