

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/06/2020

Submitted Date:

02/06/2020

Document Number:

696102150**FIELD INSPECTION FORM**Loc ID 450230 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:                     **Operator Information:**OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
James, Brian		bjames@hpres.com	<a href="#">All Inspections</a>
Leonard, Mike		mike.leonard@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430494	WELL	TA		OW	123-36170	Peterson CX GH 30-28D	TA
450230	LOCATION	AC			-	Peterson Production Pad 5-63-30 SWNE	IO

**General Comment:**

This is an ACCIDENT Inspection (FIRE).  
 Reference Form 22 Accident Tracking doc #402304849.  
 Reference Form 19 Release Report (Initial) doc. #402304918.  
 Reference Form 19 Release Report (Supplemental) doc. #402305276.  
 GPS Coordinates SE Corner of Tank Battery: 40.373380, -104.477000

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment (Damaged VRU equipment) at battery site. Refer to Rule 603.f. See photos #1-7.		
Corrective Action:	Remove unused equipment (Damaged VRU equipment) at battery site. Comply w/ Rule 603.f. See photos #1-7.		Date: 05/07/2020
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: VRU	# 3		corrective date
Comment:	1: Unit appears severely damaged from fire incident. 2: Units appear moderately damaged from fire incident.		
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 430494 Type: WELL API Number: 123-36170 Status: TA Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.  
Form 5A doc. #401408554 indicates TA date: 06/30/2017. Approved.  
Form 42 MIT-Notice doc. #402186836, Approved.  
Form 21 doc. #402221820 indicates MIT done: 10/04/2019. Approval Pending.

Corrective Action:  Date:

Facility ID: 450230 Type: LOCATION API Number: - Status: AC Insp. Status: IO

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 02/06/2020 at approximately 13:52 hrs. I, Bret Evins and Jason Gomez, conducted an onsite inspection at:            Operator Name: HIGHPOINT OPERATING CORPORATION            Location Name: Peterson Production Pad /5-63-30 SWNE            Location ID: 450230            Well Name: Peterson CX GH 30-28D            API: 05-123-36170            Location County: Weld County, Colorado            Weather: Mostly cloudy w/ light snow coverage from prior storm.</p> <p>While there, I observed:            Damage to VRU equipment.            Residual damage to adjacent scrubber tank and separator.            All Equipment shut-down at time of inspection.            GPS Coordinates SE Corner of Tank Battery: 40.373380, -104.477000</p> <p>Reference Form 22 Accident Tracking doc #402304849.            Reference Form 19 Release Report (Initial) doc. #402304918.            Reference Form 19 Release Report (Supplemental) doc. #402305276.</p> <p>During this inspection the following possible compliance issues were observed:            1.) Unused equipment (Damaged VRU equipment) at battery site. Refer to Rule 603.f.            Remove unused equipment (Damaged VRU equipment) at battery site. Comply w/ Rule 603.f.            Corrective Action date: 05/07/2020.            See photos #1-7.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	02/06/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
402306239	INSPECTION SUBMITTED	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060219">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060219</a>

696102151	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060218">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060218</a>
-----------	-------------	---

