

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/06/2020

Submitted Date:

02/06/2020

Document Number:

696301243**FIELD INSPECTION FORM**
 Loc ID 438941 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
James, Brian		bjames@hpres.com	All Inspections
Kraich, Adam		adam.kraich@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438937	WELL	PR	08/01/2018	OW	123-40222	ANSCHUTZ STATE 5-62-26-3225CH2	PR
438938	WELL	PR	08/01/2018	OW	123-40223	Anschutz State 5-62-26-1724BH2	PR
438939	WELL	PR	08/01/2018	OW	123-40224	Anschutz State 5-62-26-1609BH2	PR
438960	WELL	PR	08/01/2018	OW	123-40233	ANSCHUTZ STATE 5-62-26-1724CH2	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Unmarked Risers by Flare and VRT, see photos		
Corrective Action:	Comply with Rule 603.f.	Date:	02/11/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Other	# 2		
Comment:	Generatos		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Line Heater		
Corrective Action:		Date:	
Type: VRU	# 3		
Comment:			
Corrective Action:		Date:	

Type: VRT	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 3		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 4		
Comment:	Appear to be plumbed to surface		
Corrective Action:			Date:
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:			Date:
Type: LACT	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 10		
Comment:			
Corrective Action:			Date:
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Flare	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:
Contents	#	Capacity	Type	Tank ID
CRUDE OIL	12	400 BBLs	STEEL AST	SE GPS
				40.372830,-104.299440
Comment:				
Corrective Action:				Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 438937 Type: WELL API Number: 123-40222 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 438938 Type: WELL API Number: 123-40223 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 438939 Type: WELL API Number: 123-40224 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 438960 Type: WELL API Number: 123-40233 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine Field Inspection. Winter Conditions, snow covered ground at the time of this Inspection. Unmarked Riser on location. Comply with Rule 603.f. Corrective Action date of 02.11.2020.	petrie	02/06/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402306237	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060212
696301244	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060206