



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	pumpjack at well is disassembled and laying on ground along with pumpjack fence alternate means of production at wellhead.		
Corrective Action:	Comply with Rule 603.f	Date:	01/16/2020
Type	WEEDS		
Comment:	Dead weeds all around location		
Corrective Action:	Comply with Rule 603.f	Date:	12/23/2019

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Ancillary equipment	# 1		
Comment:	Automation		
Corrective Action:		Date:	
Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 239878 Type: WELL API Number: 123-07666 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Thursday 2/6/2020 at approximately 1230 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:</p> <p style="text-align: right;">John A Kunzman-1 at API #05-123-07666 in Weld County Colorado.</p> <p>While there, I observed a producing wellsite. This is a follow up inspection per Doc. # 697600672</p> <p>During this inspection the following possible compliance issues were observed and are delinquent:                      603.f Housekeeping: dead weeds all around location CA date 12/18/2019.                      603.f Unused equipment: disassembled pump jack and fence is lying on ground and sitting on cement pads CA date 1/16/2020 see attached photos.                      Location is snow covered, weather is overcast and cold.                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      Continuing education COGCC Inspection Report Summary.                      This is a summary of inspection report.</p>	revasr	02/06/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402306216	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060177">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060177</a>
699301043	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060169">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060169</a>