

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/12/2020

Submitted Date:

02/12/2020

Document Number:

689704200

FIELD INSPECTION FORM

Loc ID 335419 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Findings:

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262303	WELL	PR	01/08/2002	GW	045-08011	CHEVRON GM44-20	PR
277260	WELL	PR	01/15/2006	GW	045-10657	CHEVRON GM 544-20	PR
277261	WELL	PR	01/23/2006	GW	045-10656	CHEVRON GM 444-20	PR
277262	WELL	PR	01/10/2006	GW	045-10655	CHEVRON GM 343-20	PR

General Comment:

This is a summary of inspection report.
On Wednesday 02/12/2020 at approximately 1330 hours, I, Inspector Mike Longworth, conducted a field inspection at Terra Rocky Mountain LLC CHEVRON-66S96W 20SESE, at Location # 335419 in Garfield County, Colorado
During this inspection the following possible compliance issues were observed:
Bubbling in cellar around GM 44-20 well head.
Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.
C.A. Date 02/13/2020
I spoke with Nate Leonard of TEP on 02/12/2020 at approximately 1500 hours via phone to advise of the bubbling around well head GM44-20.
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Lease Road:

Type	Access		
comment:	Snow Covered		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	970-285-9377		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Equipment:

			corrective date
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	Shared facilities with location 335170 MV 22-20				
Corrective Action:					Date:

Paint

Condition	<input style="width: 150px;" type="text"/>
Other (Content)	<input style="width: 800px;" type="text"/>

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date: <input style="width: 100px;" type="text"/>

Venting:

Yes/No			
Comment:			
Corrective Action:			Date: <input style="width: 100px;" type="text"/>

Flaring:

Type			
Comment:			
Corrective Action:			Date: <input style="width: 100px;" type="text"/>

Inspected Facilities			
Facility ID: <u>262303</u>	Type: <u>WELL</u>	API Number: <u>045-08011</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	Bubbling in cellar around well head.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	<u>02/13/2020</u>
Facility ID: <u>277260</u>	Type: <u>WELL</u>	API Number: <u>045-10657</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	Producing well		
Corrective Action:		Date:	
Facility ID: <u>277261</u>	Type: <u>WELL</u>	API Number: <u>045-10656</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	Producing well		
Corrective Action:		Date:	
Facility ID: <u>277262</u>	Type: <u>WELL</u>	API Number: <u>045-10655</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	Producing well		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Limited BMP inspection due to snow cover.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689704201	Inspection 689704200 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5066321