

Inspection Photos

Location Name: LARAMIE ENERGY LLC BRUTON /19-14 PAD,

Location ID: 417603



Network time is not synchronize
Local:Feb 13, 2020 at 2:05:11 PM MS
+39.2550,-107.806

Photo #0584 from entrance to location



Network time is not synchronize
Local:Feb 13, 2020 at 2:06:07 PM MS
+39.2578,-107.814

Photo #0585 Chemical tank by wellheads NFPA labels weathered and not legible.

Inspection Photos
Location Name: LARAMIE ENERGY LLC BRUTON /19-14 PAD,
Location ID: 417603



Photo #0586 Used filters and trash inside multiple tank containments.



Photo #0593 Used filters and trash inside multiple tank containments.

Inspection Photos

Location Name: LARAMIE ENERGY LLC BRUTON /19-14 PAD,

Location ID: 417603



Photo #0587 Multiple containments with oily fluids inside them.



Photo #0588 Multiple containments with oily fluids inside them.

Inspection Photos

Location Name: LARAMIE ENERGY LLC BRUTON /19-14 PAD,

Location ID: 417603



Photo #0594 Multiple containments with oily fluids inside them.



Photo #0589 Unused automated valve.

Inspection Photos

Location Name: LARAMIE ENERGY LLC BRUTON /19-14 PAD,

Location ID: 417603



Photo #0592 open ended flowline.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources