

Inspection Photos

API: 071-08043

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 2/14/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08043 | Date: 2/14/2020

Inspection Photos



Photo 1. There is stormwater erosion which is occurring along the main road as it ascends the hill which is contributing to erosion further down the road. BMP's need to be installed. Lat/Long:37.14162,-104.86902.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08043 | Date: 2/14/2020

Inspection Photos



Photo 2. The culvert outlet which stormwater is direct from the Pacheco well sites is concentrating stormwater and causing erosion at this area Lat/Long:37.14117,-104.87398.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08043 | Date: 2/14/2020

Inspection Photos



Photo 3. The gate leading to the location is off the hinges and needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08043 | Date: 2/14/2020

Inspection Photos



Photo 4. The gate leading to the location is off the hinges and needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08043 | Date: 2/14/2020

Inspection Photos



Photo 5. The water level at the pit is nearing 2 ft. freeboard.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08043 | Date: 2/14/2020