

Inspection Photos

API: 071-07803

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 2/14/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07803 | Date: 2/14/2020

Inspection Photos



Photo 1. There a deep erosion channel at the outlet of the culvert along the main access road at Lat/Long:37.14466,-104.86788.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07803 | Date: 2/14/2020

Inspection Photos



Photo 2. There is a deep erosion channel along the side of the main access to the location. Arrow points to 4.5 ft. shovel to show depth of erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07803 | Date: 2/14/2020

Inspection Photos



Photo 3. The stormwater outlet from this culvert is contributing to erosion of this gully. Lat/Long:37.14924,-104.86830.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07803 | Date: 2/14/2020

Inspection Photos



Photo 4. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07803 | Date: 2/14/2020