

# Inspection Photos

API: 071-07640

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 2/14/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-07640 | Date: 2/14/2020

## Inspection Photos



**Photo 1.** There is stormwater erosion which is occurring along the main road as it ascends the hill. BMP's need to be installed. Lat/Long:37.13882,-104.85030.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07640 | Date: 2/14/2020



## Inspection Photos



**Photo 2.** Facing toward the location. A berm is installed along the cut slope to contain erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07640 | Date: 2/14/2020

## Inspection Photos



**Photo 3.** Well sign is installed at meter shed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07640 | Date: 2/14/2020



## Inspection Photos



**Photo 4.** Facing west toward the well.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07640 | Date: 2/14/2020



## Inspection Photos



**Photo 5.** The pit liner is torn and degraded. There did not appear to be produced water in the pit at time of inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07640 | Date: 2/14/2020