

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/15/2020

Submitted Date:

02/15/2020

Document Number:

696301318

FIELD INSPECTION FORM

Loc ID 445257 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
,		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
445253	WELL	PR	12/15/2017	OW	123-42980	Hazzard Federal LC22-735	PR
445254	WELL	PR	02/14/2017	OW	123-42981	Dukes Federal LC10-745	PR
445255	WELL	PR	12/15/2017	OW	123-42982	Dukes Federal LC10-735	PR
445256	WELL	PR	12/19/2017	OW	123-42983	Hazzard Federal LC22-745	PR
445258	WELL	PR	12/20/2017	OW	123-42984	Hazzard Federal LC22-740	PR

General Comment:

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
	Comment: Adequate (x5)		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

	Type WELLHEAD		
	Comment: Panels		
Corrective Action:		Date:	

Equipment:

					corrective date
Type: Plunger Lift	# 5				
Comment:					
Corrective Action:		Date:			
Type: Bradenhead	# 5				
Comment:	Appears to be plumbed to surface				
Corrective Action:		Date:			
Type: Gas Meter Run	# 5				
Comment:					
Corrective Action:		Date:			

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	445253	Type:	WELL	API Number:	123-42980	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:								Date:	
Facility ID:	445254	Type:	WELL	API Number:	123-42981	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:								Date:	
Facility ID:	445255	Type:	WELL	API Number:	123-42982	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:								Date:	
Facility ID:	445256	Type:	WELL	API Number:	123-42983	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:								Date:	
Facility ID:	445258	Type:	WELL	API Number:	123-42984	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine Field Inspection. Winter Conditions, snow covered ground at the time of inspection.	petrie	02/15/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696301319	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5069277