

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/12/2020

Submitted Date:

02/12/2020

Document Number:

689704200**FIELD INSPECTION FORM**Loc ID 335419 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262303	WELL	PR	01/08/2002	GW	045-08011	CHEVRON GM44-20	PR
277260	WELL	PR	01/15/2006	GW	045-10657	CHEVRON GM 544-20	PR
277261	WELL	PR	01/23/2006	GW	045-10656	CHEVRON GM 444-20	PR
277262	WELL	PR	01/10/2006	GW	045-10655	CHEVRON GM 343-20	PR

General Comment:

This is a summary of inspection report.

On Wednesday 02/12/2020 at approximately 1330 hours, I, Inspector Mike Longworth, conducted a field inspection at Terra Rocky Mountain LLC CHEVRON-66S96W 20SESE, at Location # 335419 in Garfield County, Colorado

During this inspection the following possible compliance issues were observed:

Bubbling in cellar around GM 44-20 well head.

Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

C.A. Date 02/13/2020

I spoke with Nate Leonard of TEP on 02/12/2020 at approximately 1500 hours via phone to advise of the bubbling around well head GM44-20.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location**Lease Road:**

Type	Access		
comment:	Snow Covered		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	970-285-9377		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 4		corrective date
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	Shared facilities with location 335170 MV 22-20				
Corrective Action:				Date:	

Paint

Condition		
Other (Content)		

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities			
Facility ID: 262303	Type: WELL	API Number: 045-08011	Status: PR Insp. Status: PR
Producing Well			
Comment:	Bubbling in cellar around well head.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	02/13/2020
Facility ID: 277260	Type: WELL	API Number: 045-10657	Status: PR Insp. Status: PR
Producing Well			
Comment:	Producing well		
Corrective Action:		Date:	
Facility ID: 277261	Type: WELL	API Number: 045-10656	Status: PR Insp. Status: PR
Producing Well			
Comment:	Producing well		
Corrective Action:		Date:	
Facility ID: 277262	Type: WELL	API Number: 045-10655	Status: PR Insp. Status: PR
Producing Well			
Comment:	Producing well		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Limited BMP inspection due to snow cover.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402311580	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5066365
689704201	Inspection 689704200 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5066321