

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/10/2020

Submitted Date:

02/13/2020

Document Number:

693901421

**FIELD INSPECTION FORM**

Loc ID: 333994 Inspector Name: ROY, CATHERINE On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		SanJuanCOGCC@bp.com	All Inspections
Beebe, Sabre		sabre.beebe@bpx.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295137	WELL	PR	03/13/2014	GW	067-09517	BRUCE COLVIN A 4	RI
295163	WELL	PR	03/13/2014	GW	067-09518	BRUCE COLVIN A 3	RI
295165	WELL	PR	08/01/2017	GW	067-09520	BRUCE COLVIN A 2	RI

**General Comment:**

On 2/10/2020 Catherine Roy conducted a reclamation and stormwater inspection. During this inspection the following compliance issues were observed:

- Stormwater erosion needs to be controlled by February 28, 2020.
- Weeds need to be controlled at the appropriate time, and no later than June 1, 2020.

See below, and attached photos for additional detail.

**Inspected Facilities**

Facility ID: 295137 Type: WELL API Number: 067-09517 Status: PR Insp. Status: RI

Facility ID: 295163 Type: WELL API Number: 067-09518 Status: PR Insp. Status: RI

Facility ID: 295165 Type: WELL API Number: 067-09520 Status: PR Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use?      In      Production areas stabilized ?       
 1003c. Compacted areas have been cross ripped?       
 1003d. Drilling pit closed?      Subsidence over on drill pit?       
 Cuttings management:       
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing?       
 Production areas have been stabilized?      Segregated soils have been replaced?     

RESTORATION AND REVEGETATION

Cropland

Top soil replaced      Recontoured      Perennial forage re-established     

Non-Cropland

Top soil replaced      Recontoured      80% Revegetation     

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA%       
 TRANSECT RESULTS OF REFERENCE AREA%       
 TOTAL % OF DESIRABLE VEGETATION COVER       
 VEGETATIVE COVER     

1003 f. Weeds Noxious weeds?     

Comment Approximately 75 musk thistles observed along the access road. Revegetation is in a grazed/dormant condition at this time.

Corrective Action Control weeds at the appropriate time and no later than June 1, 2020.

Date 06/01/2020

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started:      Date Final Reclamation Completed:     

Final Land Use:     

Reminder:     

Comment:

Well plugged      Pit mouse/rat holes, cellars backfilled     

Debris removed      No disturbance /Location never built     

Access Roads Regraded      Contoured      Culverts removed     

Gravel removed     

Location and associated production facilities reclaimed      Locations, facilities, roads, recontoured     

Compaction alleviation      Dust and erosion control     

Non cropland: Revegetated 80%      Cropland: perennial forage     

Weeds present      Subsidence     

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA%       
 TRANSECT RESULTS OF REFERENCE AREA%       
 TOTAL % OF DESIRABLE VEGETATION COVER       
 VEGETATIVE COVER     

Comment:

Corrective Action:

Date     

Overall Final Reclamation     

Well Release on Active Location

Multi-Well Location

<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <span style="color: blue;">Erosional channeling and rilling is occurring in the southern project area. Active snow melt is eroding a channel in the southern project area.</span>						Date: <u>02/28/2020</u>
Corrective Action: <span style="color: red;">Stormwater controls need to be installed to stabilize erosion within the project area. Stormwater controls need to be selected, sized, installed, and maintained according to good engineering practices such as those described by CDOT in their erosion control manuals.</span>						
<b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402312151	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5066970">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5066970</a>
693901422	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5066962">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5066962</a>