

Inspection Photos
Operator: Kinder Morgan
Location #: 313490
Date: 2/20/2020



Photo 1. View of the project area from the northeastern edge of the working area facing center.



Photo 2. View of the eastern project area from the northeastern edge facing southward. Sparse revegetation within fenced areas. Additional reclamation is needed.




Photo 3. View of Russian knapweed infestation within the northern project area.



Photo 4. View of bare soils that appear to be salt impacted within the northern project area. Revegetation will likely require soil testing and amendment.



Photo 5. View of bare soils that appear to be salt impacted within the western project area. Revegetation will likely require soil testing and amendment.



Photo 6. View of salt cedar weed within the western project area, needs to be controlled and removed.



Photo 7. View of the reference area, comprised of pinyon juniper woodland, mixed cliffrose shrubland, and grasses such as Indian ricegrass and sand dropseed in the understory.