

Inspection Photos

Location Name: Yellow Jacket Produced Water Pump #103B

Spill/Release Point ID: 471621



Packing failed on produced water pump.



Secondary containment and sump drain.

Inspection Photos

Location Name: Yellow Jacket Produced Water Pump #103B

Spill/Release Point ID: 471621



Sump pump failed to activate, resulting in overflowed secondary containment areas.



Stained and wet soil along edge of containment areas.



Inspection Photos

Location Name: Yellow Jacket Produced Water Pump #103B

Spill/Release Point ID: 471621



Wet soil near glycol pumps.



Stained and wet soil near blow down tank.

