

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Condensate Tank missing Capcaity, see photos		
Corrective Action:	Comply with Rule 210.d	Date:	03/23/2020
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused Polis rod at Pumping Unit. See photos		
Corrective Action:	Comply with Rule 603.f.	Date:	03/23/2020
Type	STORAGE OF SUPL		
Comment:	Unmarked Risers - East and SE side of location. See photos		
Corrective Action:	Comply with Rule 603.f.	Date:	02/27/2020

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:		Date:	

Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	500 BBLs	STEEL AST		40.363870,-104.210100
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		
		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 430465 Type: WELL API Number: 123-36165 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 02/20/2020 at approximately 12:57, I, Inspector Erica Petrie, conducted a Field Inspection at HighPoint Operating Corp. Location ID #430466 in Weld County, Colorado. While there, I observed Production Operations. During this inspection the following possible compliance issues were observed: Unused Polish Rod at Pumping Unit. See photos. Comply with Rule 603.f. Corrective Action date 03.23.2020 Unmarked Riser in the SE corner and on the Eastside of Location. See photos. Comply with Rule 603.f. Corrective Action date 02.27.2020 Condensate Tank is missing Capacity, see photos. Comply with Rule 210.d. Corrective Action Date 03.23.202 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report. Continuing Educational Inspection</p>	petrie	02/24/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696301408	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5076012