

Inspection Photos
Operator: Kinder Morgan
Location #: 428396
Date: 2/20/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation appears to be progressing with grasses such as western wheatgrass, Indian ricegrass, and sand dropseed.



Photo 3. View of northern project area from the northeastern corner facing southwestward. Numerous annual weeds/debris are threatening successful revegetation in portions of the interim reclamation area and need to be managed.



Photo 4. View of reference area vegetation comprised of pinyon juniper woodland, with sagebrush and mixed grass/forbs in the understory.