

Inspection Photos

Location Name: Exxon Tank Farm PA 313-33

Location ID: 324188 & Spill/Release ID: 471286

Inspection Date: February 13, 2020




Photo #1 – Location sign.




Photo #2 – Location sign.



Inspection Photos

Location Name: Exxon Tank Farm PA 313-33

Location ID: 324188 & Spill/Release ID: 471286

Inspection Date: February 13, 2020



Photo #3 – Impacted snow and fluid within the tank battery secondary containment.



Photo #4 - Impacted snow and fluid within the tank battery secondary containment.



Inspection Photos

Location Name: Exxon Tank Farm PA 313-33

Location ID: 324188 & Spill/Release ID: 471286

Inspection Date: February 13, 2020



Photo #5 - Multiple repairs of the northwest Produced Water Steel AST.



Photo #6 - Multiple repairs of the northwest Produced Water Steel AST.

