

Stagner 2 & 6
API: 05-103-07101 & 07362
Inspection: 700400164



Photo 1. Location.



Stagner 2 & 6
API: 05-103-07101 & 07362
Inspection: 700400164



Photo 2. Pump jack of well Stagner 2.



Stagner 2 & 6
API: 05-103-07101 & 07362
Inspection: 700400164



40.099, -108.81595, 5136.1ft, 269°
02/24/2020 12:36:08 PM

Photo 3. Hole on top of casing of well Stagner 2.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Stagner 2 & 6
API: 05-103-07101 & 07362
Inspection: 700400164



Photo 4. Oily soil next to well Stagner 2.



Stagner 2 & 6
API: 05-103-07101 & 07362
Inspection: 700400164



Photo 5. Bucket next to well Stagner 2.



Stagner 2 & 6
API: 05-103-07101 & 07362
Inspection: 700400164



Photo 6. Well Stagner 6.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Stagner 2 & 6
API: 05-103-07101 & 07362
Inspection: 700400164



Photo 7. Casing open to atmosphere well Stagner 6.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Stagner 2 & 6
API: 05-103-07101 & 07362
Inspection: 700400164



Photo 8. Tank.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Stagner 2 & 6
API: 05-103-07101 & 07362
Inspection: 700400164



Photo 9. Stained soil next to tank.

Stagner 2 & 6
API: 05-103-07101 & 07362
Inspection: 700400164



Photo 10. Unused equipment. Unknown if silver tank on hill is associated with this location.