

Inspection Photos

API: 055-06157

Operator: PETROGLYPH OPERATING

Inspection Date: 2/27/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06157 | Date: 2/27/2020

Inspection Photos



Photo 1. Facing northwest at the beginning of the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06157 | Date: 2/27/2020

Inspection Photos



Photo 2. Northwest along the access road. This area is sparse of vegetation. This area may need decompaction and leveling to fill in erosion shown in the next photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06157 | Date: 2/27/2020

Inspection Photos



Photo 3. This erosion channel along the access road needs to be repaired and stabilized with vegetation. This channel needs to be filled in and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06157 | Date: 2/27/2020

Inspection Photos



Photo 4. Facing north toward the location. Vegetation appears to be fully established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06157 | Date: 2/27/2020

Inspection Photos



Photo 5. Facing south at the location. Vegetation appears to be fully established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06157 | Date: 2/27/2020

Inspection Photos



Photo 6. The disturbance area which heads northwest appears to be revegetated. This area was not fully inspected further.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06157 | Date: 2/27/2020

Inspection Photos



Photo 7. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06157 | Date: 2/27/2020