

FORM  
INSPRev  
X/15State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/28/2020

Submitted Date:

02/28/2020

Document Number:

700700200

## FIELD INSPECTION FORM

 Loc ID 334830 Inspector Name: Ramsey, Scott On-Site Inspection  2A Doc Num:
**Operator Information:**
 OGCC Operator Number: 10456  
 Name of Operator: CAERUS PICEANCE LLC  
 Address: 1001 17TH STREET #1600  
 City: DENVER State: CO Zip: 80202
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211428	WELL	PR	09/22/1997	GW	045-07188	GRAHAM 32-12	PR
265591	WELL	PR	10/09/2008	GW	045-09029	GRAHAM 32-12D (L32)	PR
265592	WELL	SI	08/01/2018	GW	045-09030	COUEY 32-5D (L32)	SI
265593	WELL	PR	06/18/2003	GW	045-09028	GRAHAM 32-12B (L32)	PR
265594	WELL	PR	06/16/2003	GW	045-09031	SHIDELER 32-11D (L32)	PR
265595	WELL	PR	06/15/2003	GW	045-09032	COUEY 31-9D (L32)	PR

**General Comment:**

## COGCC Inspection Report Summary

On Friday 2/28/20 at approximately 1:00 PM, I, Inspector Scott Ramsey, conducted a follow up inspection at Caerus L32, at Location # 334830 in Garfield Colorado.

While there, I observed normal production operations. All C/A(s) from previous inspection document # 694900589 have been completed.

The following Compliance issue was observed:

- Drain valve in tank has a leak

I spoke with lead Scott Muller and he contacted pumper, Scott said pumper was on his way to fix leak. Pumper arrived and fixed leak, no C/A was issued.

This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:	911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
<b>Equipment:</b>			
Type:	Horizontal Heated Separator	# 1	corrective date
Comment:			

Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	211428	Type:	WELL	API Number:	045-07188	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	265591	Type:	WELL	API Number:	045-09029	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	265592	Type:	WELL	API Number:	045-09030	Status:	SI	Insp. Status:	SI
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	265593	Type:	WELL	API Number:	045-09028	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	265594	Type:	WELL	API Number:	045-09031	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	265595	Type:	WELL	API Number:	045-09032	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Culverts				
		Ditches				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700700205	Photos for L32	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5081484">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5081484</a>