

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/29/2020

Submitted Date:

02/29/2020

Document Number:

693502407**FIELD INSPECTION FORM**Loc ID 455317 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10459

Name of Operator: EXTRACTION OIL &amp; GAS INC

Address: 370 17TH STREET SUITE 5300

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
Carlisle, J	970-534-6006	COGCCInspections@extracti onog.com	ALL INSPECTIONS

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
455314	WELL	DG	06/04/2019		014-20756	Livingston S19-25-4N	DG

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:	Adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Sound walls		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 455314 Type: WELL API Number: 014-20756 Status: DG Insp. Status: DG**Completion**Operation: Drillout

Date Flowback:

Contractor:

Comment: Patriot Coil tubing unit. Supervisor Casey Wilkins. At time of inspection crew was drilling plug 35 15900. Liberty quite fleet pumps spotted and running.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Tracking Pad	Pass	Self Inspection	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Inspection due to complaints and sound study being performed. I performed sound study on south side of location next to residents home 2-28 10:08AM to 2-29 1:10PM. At time of inspection it appeared location is in compliance with the COGCC noise rules. See photos and sound study for times and location. Weather conditions: cloudy and location dry.	silverr	02/29/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693502408	Sound data	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5081782">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5081782</a>
693502409	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5081783">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5081783</a>