

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/18/2020

Submitted Date:

02/24/2020

Document Number:

688000374**FIELD INSPECTION FORM**Loc ID 317231 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 53790Name of Operator: MARKUS PRODUCTION, INCAddress: 39 FAIRWAY LANECity: LITTLETON State: CO Zip: 80123**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone          | Email                     | Comment |
|--------------|----------------|---------------------------|---------|
| Brown, Mark  | (720) 350-8858 | mark@markusproduction.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|---------|---------------------|-------------|
| 107649      | PIT  | AC     |             |            | -       | JOLLY 41X-6         | EI          |
| 119049      | PIT  | AC     |             |            | -       | CHARLES JOLLY 41X-6 | EI          |

**General Comment:**[Environmental inspection related to Rem #13154 \(former produced water pit closure\) pits 119049 and 107649.](#)

| Inspected Facilities |               |       |            |             |          |         |           |               |           |
|----------------------|---------------|-------|------------|-------------|----------|---------|-----------|---------------|-----------|
| Facility ID:         | <u>107649</u> | Type: | <u>PIT</u> | API Number: | <u>-</u> | Status: | <u>AC</u> | Insp. Status: | <u>EI</u> |
|                      |               |       |            |             |          |         |           |               |           |
| Facility ID:         | <u>119049</u> | Type: | <u>PIT</u> | API Number: | <u>-</u> | Status: | <u>AC</u> | Insp. Status: | <u>EI</u> |
|                      |               |       |            |             |          |         |           |               |           |

|  |
|--|
|  |
|--|

**Environmental****Spills/Releases:**

|                                   |                               |
|-----------------------------------|-------------------------------|
| Type of Spill: _____              | Estimated Spill Volume: _____ |
| Comment: _____                    |                               |
| Corrective Action: _____          | Date: _____                   |
| Reportable: _____                 | GPS: Lat _____ Long _____     |
| Proximity to Surface Water: _____ | Depth to Ground Water: _____  |

**Water Well Complaint:**

|                        |                   |             |
|------------------------|-------------------|-------------|
|                        | Lat               | Long        |
| DWR Receipt Num: _____ | Owner Name: _____ | GPS : _____ |

**Field Parameters:**

|                        |                |
|------------------------|----------------|
| Sample Location: _____ | Comment: _____ |
|------------------------|----------------|

**Spill/Remediation:**

|                    |  |                  |
|--------------------|--|------------------|
| Comment:           | Rem 13154. This remediation project needs to be completed in time to take advantage of spring moisture for successful reclamation. |                  |
| Corrective Action: | Provide a supplemental eForm 27 including an updated schedule for implementation/completion of this remediation project.           | Date: 02/21/2020 |

|   |
|---|
| Emission Control Burner (ECB): _____                            |
| Comment: _____  |
| Pilot: _____ Wildlife Protection Devices (fired vessels): _____ |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402321720    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5075509">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5075509</a> |
| 688000375    | Location photographs | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5075500">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5075500</a> |