

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/24/2020

Submitted Date:

02/24/2020

Document Number:

700700166**FIELD INSPECTION FORM**
 Loc ID 335055 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 950 17TH STREET, SUITE 1900City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268723	WELL	PR	03/01/2017	GW	045-09287	CSF 22C-07-07-91	PR
279971	WELL	PR	03/01/2017	GW	045-11120	CSF 11B-07-07-91	PR
279974	WELL	PR	03/01/2017	GW	045-11122	CSF 21B-07-07-91	PR
283836	WELL	PR	04/01/2018	GW	045-11983	CSF 31B-07-07-91	PR
283837	WELL	PR	04/01/2017	GW	045-11984	CSF 32B-07-07-91	PR
298151	WELL	SI	11/01/2019	GW	045-17084	CSF 21C-07-07-91	SI

General Comment:**COGCC Inspection Report Summary**

On Monday 2/24/20 at approximately 1:30 PM, I, Inspector Scott Ramsey, conducted a follow up inspection at Ursa U pad, at Location # 335055 in Garfield Colorado.

During this inspection the following possible compliance issues were observed:

- Debris

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:	snow covered		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:	concrete blanket and metal building west of separators		
Corrective Action:	Comply with Rule 603.f .	Date:	03/24/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	livestock fence		
Corrective Action:		Date:	

Equipment:

Type: Pig Station	# 1		corrective date
Comment:			

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	chemical tank at wellheads		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	HEATED STEEL AST		,
Comment:	one tank is not heated				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
------	--

Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 268723 Type: WELL API Number: 045-09287 Status: PR Insp. Status: PR**Producing Well**Comment: producedCorrective Action: Date: Facility ID: 279971 Type: WELL API Number: 045-11120 Status: PR Insp. Status: PR**Producing Well**Comment: producedCorrective Action: Date: Facility ID: 279974 Type: WELL API Number: 045-11122 Status: PR Insp. Status: PR**Producing Well**Comment: producedCorrective Action: Date: Facility ID: 283836 Type: WELL API Number: 045-11983 Status: PR Insp. Status: PR**Producing Well**Comment: producedCorrective Action: Date: Facility ID: 283837 Type: WELL API Number: 045-11984 Status: PR Insp. Status: PR**Producing Well**Comment: producedCorrective Action: Date: Facility ID: 298151 Type: WELL API Number: 045-17084 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: Comment: shut in Last produced 10/1/2019Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402322229	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5076164
700700171	Photos for U Pad	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5076160