

Inspection Photos

API: 055-06221

Operator: PETROGLYPH OPERATING

Inspection Date: 2/27/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06221 | Date: 2/27/2020

Inspection Photos



Photo 1. Facing southeast along the access road. Rock check dams were installed along the side of the road but have since failed. The rock has been displaced as shown by arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06221 | Date: 2/27/2020

Inspection Photos



Photo 2. Stormwater is flowing down the road causing erosion near the State 7W location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06221 | Date: 2/27/2020

Inspection Photos



Photo 3. The check dams have filled in with sediment and are starting to erode around the check dam shown by arrow. The side of road should be seeded and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06221 | Date: 2/27/2020

Inspection Photos



Photo 4. Facing east toward the location. Vegetation appears to be establishing well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06221 | Date: 2/27/2020

Inspection Photos



Photo 5. Facing southeast at the location. Vegetation appears to be establishing well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06221 | Date: 2/27/2020

Inspection Photos



Photo 6. Facing east at the south side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06221 | Date: 2/27/2020

Inspection Photos



Photo 7. Facing northwest at the south side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06221 | Date: 2/27/2020

Inspection Photos



Photo 8. Facing southeast at the south side of the location. The access road continues toward the State 10WB. This check damn has filled in with sediment. The side of road should be seeded and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06221 | Date: 2/27/2020

Inspection Photos



Photo 9. There is plastic netting debris along the southeast cut slope that should be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06221 | Date: 2/27/2020