

Inspection Photos  
Operator: Hilcorp Energy  
Location #: 067-09339  
Date: 2/27/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern fill slope, revegetation appears to be progressing with grasses such as smooth brome.



Photo 3. View of Kochia debris, up to 3 feet tall, along the eastern edge of the working area.



Photos 4/5. View of unmarked guyline anchors within the project area.



Photo 6. View of reference area vegetation comprised of pinyon and juniper woodland with smooth brome dominated understory.