

Inspection Photos
Operator: Hilcorp Energy
Location #: 067-09459
Date: 2/27/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western fill slope, revegetation appears to be progressing with a mixture of wheatgrasses in a dormant vegetative condition. Spot seeding is needed along the western edge of the working area where bare soils persist.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 6. View of reference area vegetation comprised of pinyon and juniper woodland with smooth brome dominated understory.