

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/25/2020

Submitted Date:

02/25/2020

Document Number:

696301436

FIELD INSPECTION FORM

Loc ID 439896 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 14 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
,		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
439895	WELL	PR	10/01/2016	OW	123-40591	Remora LC34-735	PR
439897	WELL	PR	10/01/2016	OW	123-40592	Remora LC34-715	PR
439898	WELL	PR	10/01/2016	OW	123-40593	Haley LC27-711	PR
439902	WELL	PR	10/01/2016	OW	123-40597	Haley LC27-715	PR
439904	WELL	PR	10/01/2016	OW	123-40599	Remora LC34-745	PR
439905	WELL	PR	10/01/2016	OW	123-40600	Haley LC27-735	PR
439906	WELL	PR	09/03/2015	OW	123-40601	Haley LC27-745	PR
439907	WELL	PR	10/01/2016	OW	123-40602	Remora LC34-725	PR

General Comment:

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Haley LC27-715 is missing Wellhead Sign		
Corrective Action:	Comply with Rule 210.b.		Date: 03/25/2020
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused Chemical Tank at Haley LC27-711 & 715 Wellheads, see photos		
Corrective Action:	Comply with Rule 603.f.		Date: 03/25/2020
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:			Date:
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:			Date:
Equipment:			
Type: Gas Meter Run	# 8		corrective date
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 8		
Comment:	Appearto be plumbed to surface		
Corrective Action:			Date:
Venting:			
Yes/No			
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	439895	Type:	WELL	API Number:	123-40591	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	439897	Type:	WELL	API Number:	123-40592	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	439898	Type:	WELL	API Number:	123-40593	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	439902	Type:	WELL	API Number:	123-40597	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	439904	Type:	WELL	API Number:	123-40599	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	439905	Type:	WELL	API Number:	123-40600	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	439906	Type:	WELL	API Number:	123-40601	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	439907	Type:	WELL	API Number:	123-40602	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine Field Inspection. Haley LC27-715 missing Wellhead Sign. Unused Chemical tank at Haley LC27-711 & 715 Wellheads, see photos. Corrective Action date 03.25.2020	petrie	02/25/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402323590	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5077627
696301437	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5077620