

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/24/2020

Submitted Date:

02/25/2020

Document Number:

700400162

FIELD INSPECTION FORM

Loc ID 336550 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10342
Name of Operator: WOODARD* SANDRA K
Address: 602 OURAY AVENUE
City: GRAND JUNCTION State: CO Zip: 81501

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
,	970-261-6589	3oilwells@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229623	WELL	SI	06/01/2019	OW	103-07280	STAGNER RECTOR 7	SI

General Comment:

[COGCC Inspection Report Summary.](#)

On 2-24-2020 at approximately 12:35, inspector Rick Moran, conducted a follow up inspection at Woodard Sandar K well Stagner 7 in Rio Blanco county of FIR document 679705374.

The following compliance issues are uncompleted:

- 1) Stained & oily soil at multiple locations. Photo 3 Complete by 10-9-2019.
- 2) Open bucket of fluid next to well head. Photo 3. Complete by 10-9-2019.

Note: Casing open to atmosphere. A gas odor was detected during this inspection. During inspection 679705374 a 3 cubic ft bag in 12 minutes with gas. Photo 4.

A follow up inspection will occur to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 700400162.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911	Date:	
Corrective Action:			

Good Housekeeping:

Type	OTHER		
Comment:	Open bucket of fluid next to well head. Bucket without wildlife protection & could be tipped over.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Stained soil around well head and flow line.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	10/09/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 229623 Type: WELL API Number: 103-07280 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402323682	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5077724
700400163	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5077717