

## Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /7NWSE

Location ID: 323851



**Photo #0678 from entrance to location**



**Photo #0679 Unused meter run.**

## Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /7NWSE

Location ID: 323851



Photo #0682 Stained soils under pump jack.



Photo #0683 Stained soils under load out valve on tank.