

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/03/2020

Submitted Date:

03/03/2020

Document Number:

699800687

**FIELD INSPECTION FORM**

Loc ID 312598 Inspector Name: De Paolo, Corey On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**  
OGCC Operator Number: 53255  
Name of Operator: MARALEX RESOURCES INC  
Address: P O BOX 338  
City: IGNACIO State: CO Zip: 81137

**Findings:**

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Graves, Jim	970-712-0099	mrinc20@qwestoffice.net	Operations Manager
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221992	WELL	SI	04/01/2010	GW	077-08594	SOUTH SHALE RIDGE 1-14	SI

**General Comment:**

COGCC Inspection Report Summary  
On Tuesday 3/3/20 at approximately 15:00 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /14NENE, Location #312598 in Mesa County Colorado.  
Refer to document #696600434 inspection conducted on 8/2/19. Not all previous corrective actions have been completed. While there, I observed normal production operations.  
During this inspection the following possible compliance issues were observed: Location over grown with debris and weeds. See photo #0699, #0700 and #0702 with a previous corrective action date of 8/11/19. MIT required on well. With a previous corrective action date of 7/15/19.  
  
A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
<b>Emergency Contact Number:</b>			
Comment:	<input type="text" value="911"/>		
Corrective Action:	<input type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Location over grown with debris and weeds. See photo #0699, #0700 and #0702		
Corrective Action:	Production facilities, shall be kept free of weeds and rubbish. Remove all debris from location.		Date: <u>07/15/2019</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Type: Vertical Separator	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 221992 Type: WELL API Number: 077-08594 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Last MIT preformed 2/11/15. Refer to document #400797407. Well last produced April 2010. Well over due for MIT.

Corrective Action: A mechanical integrity test shall be performed on each shut-in well on 5 year intervals from the date the initial mechanical integrity test was performed. Preform MIT on well.

Date: 07/15/2019

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Gravel				
		Ditches				
Berms						
		Compaction				
Ditches						
Gravel						
Compaction						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699800688	Photos for Insp. #699800687	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5084632">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5084632</a>