

Inspection Photos

Location Name: ELIOT NESS 22-17 INCIDENT FOLLOWUP ca date 4-3-20

API#: 05-071-06202

INSP. #: 695102281



PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: ELIOT NESS 22-17 INCIDENT FOLLOWUP ca date 4-3-20

API#: 05-071-06202

INSP. #: 695102281



PHOTO 3: unused equipment stored on location (propane tank is not being used). Remove unused equipment per rule 603.F. ca date 4-3-20

PHOTO 4: Polish rod oiler is running oil down wellhead assembly, This is not a ca notice as oil has not reached the ground. This is just a reminder that if this oil contaminated the soil that would result in a corrective action being administered.

Inspection Photos

Location Name: ELIOT NESS 22-17 INCIDENT FOLLOWUP ca date 4-3-20

API#: 05-071-06202

INSP. #: 695102281



PHOTO 5: 1" produced gas vent plumbed from casing head, I can hear gas venting at a whisper. (This is just documenting that there is light gas venting at the wellhead.)