

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | PHOTO 3: unused equipment stored on location (propane tank is not being used). | | |
| Corrective Action: | Remove unused equipment per rule 603.F. | Date: | 04/03/2020 |
| Type | OTHER | | |
| Comment: | PHOTO 4: Polish rod oiler is running oil down wellhead assembly, This is not a ca notice as oil has not reached the ground. This is just a reminder that if this oil contaminated the soil that would result in a corrective action being administered. | | |
| Corrective Action: | | Date: | |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|---|-------|--|
| Yes/No | YES | | |
| Comment: | PHOTO 5: 1" produced gas vent plumbed from casing head, I can hear gas venting at a whisper. (This is just documenting that there is light gas venting at the wellhead. | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 422130 Type: WELL API Number: 043-06202 Status: PR Insp. Status: PR

Producing Well

| | | |
|--------------------|--|-------|
| Comment: | | |
| Corrective Action: | | Date: |

COGCC Comments

| Comment | User | Date |
|--|----------|------------|
| This is a followup to incident report doc#402292853, There does not appear to be any spill or release due to incident. | beardsit | 03/03/2020 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 695102282 | inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5084684 |