

Inspection Photos
Operator: BP America
API#: 067-06818
Date: 3/2/2020



Photo 1. View of the project area from the northeastern corner facing center. Recent work on the well pad has resulted in compacted and damaged vegetation on the flat well pad surface.



Photo 2. View of the southern fill slope facing eastward, revegetation is grazed but appears to be progressing with grasses such as sand dropseed and western wheatgrass.



Photo 3. View of erosional channels approximately 2 feet wide and 1.5 feet deep within the southern project area.



Photo 4. View of more erosional channels within the southern project area.



Photo 5. View of damaged vegetation and evidence of vehicle compaction within the flat revegetation area.



Photo 6. View of reference area vegetation comprised pinyon juniper woodland with herbaceous understory comprised of grasses such as Indian ricegrass and muttongrass and forbs in a dormant vegetative condition.