

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/05/2020

Submitted Date:

03/05/2020

Document Number:

696301511

**FIELD INSPECTION FORM**

Loc ID 327705 Inspector Name: PETRIE, ERICA On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 96155  
Name of Operator: WHITING OIL & GAS CORPORATION  
Address: 1700 BROADWAY STE 2300  
City: DENVER State: CO Zip: 80290

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 12 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		WhitingEasternCO@Whiting.com	<a href="#">Eastern Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247254	WELL	SI	08/01/2014	GW	123-15051	NELSON RANCHES A-4	TA

**General Comment:**

*(This area is currently blank for general comments.)*

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	TANK BATTERY		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed Wire		
Corrective Action:		Date:	

**Equipment:**

Type: Vertical Heater Treater	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		

Comment:	2 Deadman not marked, see photos		Date:	03/20/2020
Corrective Action:	Comply with Rule 1003.a.			
Type: Bradenhead	# 1			
Comment:	Appears to be plumbed to Surface			
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	TA'd Wellhead			
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.838750,-103.899620
Comment:					
Corrective Action:				Date:	

**Paint**

Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:			Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 247254 Type: WELL API Number: 123-15051 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass	Seeding	Pass			

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: <u>Produced Water</u>	Lined: <u>YES</u>	Pit ID:	Lat: <u>40.838343</u>	Long: <u>-103.899780</u>
-----------------------------	-------------------	---------	-----------------------	--------------------------

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**  
 Liner Type: Plastic Liner Condition: Inadequate

Comment:

Corrective Action  Date: \_\_\_\_\_

**Fencing:**  
 Fencing Type: \_\_\_\_\_ Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action  Date: \_\_\_\_\_

**Netting:**  
 Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:

Corrective Action  Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<a href="#">Routine Field Inspection. 2 Deadman/Guy Line Anchors not marked, see photos. Comply with Rule 1003.f. Corrective Action Date 03.20.2020</a>	petrie	03/05/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696301512	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5087200">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5087200</a>