

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/05/2020

Submitted Date:

03/05/2020

Document Number:

696102484

**FIELD INSPECTION FORM**

Loc ID: 310042    Inspector Name: Evins, Bret    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON    State: TX    Zip: 77070

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections
,		dnr_cogccengineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295787	WELL	SI	01/01/2017	OW	123-25801	WELLS RANCH USX AA 23-10	TA

**General Comment:**

This is a WELL inspection.  
Well(s): 1: Temporarily Abandoned | TA.  
Battery: Abandoned. ALL equipment has been removed.  
Reclamation progressing.  
Abandoned Battery SE corner GPS coordinates: 40.468904, -104.398991  
  
Abandoned Centralized Battery formerly served 4 Location IDs (302619, 310042, 302620, 310043).  
(Well(s): 2: Temporarily Abandoned | TA ;2: Plugged & Abandoned | PA).

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bradenhead	# 1		corrective date
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 295787 Type: WELL API Number: 123-25801 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

**Comment:** Temporarily Abandoned | TA.  
 Battery Abandoned: All Equipment Removed.  
 COGCC records indicate last production: 11/2016.  
 SI/TA well per variance doc. #401474555. (NOBLE).  
 Yellow LTSI & Orange Facility Decommissioned tags for SI/TA status present at wellsite.  
 Locked-Out, Tagged-Out | LOTO.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 03/05/2020 at approximately 15:07 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: NOBLE ENERGY INC                      Location Name: WELLS RANCH USX AA-66N63W /23NWSE                      Location ID: 310042                      Well Name: Wells Ranch USX AA 23-10                      API: 05-123-25801                      Location County: Weld County, Colorado                      Weather: Mostly sunny, dry.</p> <p>While there, I observed:                      Well(s): 1: Temporarily Abandoned   TA.                      Battery: Abandoned. ALL equipment has been removed.                      Reclamation progressing.                      Abandoned Battery SE corner GPS coordinates: 40.468904, -104.398991</p> <p>Abandoned Centralized Battery formerly served 4 Location IDs (302619, 310042, 302620, 310043).                      (Well(s): 2: Temporarily Abandoned   TA ; 2: Plugged &amp; Abandoned   PA).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	03/05/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696102485	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5087355">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5087355</a>