

Inspection Photos
Operator: Williford Resources
API#: 067-06143
Date: 3/4/2020



Photo 1. View pipe debris stored within the southern project area.



Photo 2. View of the project area from the southeastern edge facing northwestward.



Photo 3. View of reference area vegetation west of the project area, largely comprised of sagebrush shrubland, in a dormant vegetative condition.